Work Order ID 95526

January-10-13 3:10:09 PM

95526

Page 1

8.

Revision ID:	D3957-4 Hinge, Door R	tH Lower		Accept	*N90004010	N 0*	Setup Start	111.71
	1/10/13	Start Qty: 4.00 Req'd Qty: 4.00	*4 *4		Cust Item ID: Customer:			14(1)
Approvals:	Process Pla	n: [Date:	*	Date:		Run Start	"NRT"
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Tool ID Tool # Pla	_	Reject Qty	Reject Insp. Number Stamp
Draw Nbr	Rev	ision Nbr	a.	•				.
D3957	<u>A</u>			<u> </u>				-
*100 *100* Bandsaw Jeaspa Bandsaw		Memo cut blank to	3.200" long	0.00	- 13/0//1	_4_	- 9	•
110	(0.00			1	QAS
110 HAAS 1 HAAS CNC vertical	I machine #1	Memo 1-Machine a FOLIO REV DWG REV		o.oo B.	a 13/01/13	4	φ	0 8 9.8
	* s _m		APPING TO FULL . AS PER dWG	DEPTH BY HAND AS PER DWG				

Work Order ID 95526 Page 2 January-10-13 3:10:09 PM D3957-4 Accept *N900040100* Item ID: Setup Start **Revision ID:** Stop Hinge, Door RH Lower **Item Name:** Start Qty: 4.00 **Start Date:** 1/10/13 **Cust Item ID:** Required Date: 1/16/13 Req'd Qty: 4.00 **Customer:** Reference: Start Run **Tooling:** Process Plan: Date: Date: Approvals: Stop SPC (Y/N): Date: Date: Tool ID Sequence ID/ Operation Tool # Plan Reject Reject Insp. Set Up/ Accept Qty Number Work Center ID **Description** Code Oty Stamp **Run Hours** QC2- Inspect parts off machine FAI/FAIB 0.00 DAG 120 13/01/13 *120* QC 0.00 Memo Quality Control OC8- Inspect parts - second check 0.00 130 20 13-1-14 4 4 *120* QC 0.00 Memo

140

Chemical Conversion Coat per OSI005 4.1

140 HandFinish

Quality Control

0.00

Memo

0.00

4 16 13-1-15

Hand Finishing

Packaging

Work Order ID 95526 *95526* Page 4 January-10-13 3:10:09 PM Item ID: D3957-4 Accept *N900040100* Setup Start **Revision ID:** Hinge, Door RH Lower Item Name: Start Qty: 4.00 **Start Date:** 1/10/13 **Cust Item ID:** Required Date: 1/16/13 **Req'd Qty:** 4.00 **Customer:** Reference: Run Date:_____ **Tooling:** Process Plan: Date: Approvals: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Tool ID Reject Reject Set Up/ Tool # Plan Accept Insp. **Work Center ID Run Hours** Code Qty Oty Number Stamp **Description** 0.00 180 QC21- Final Inspection - Work Order Release MC5 13-01-16 *120* QC 0.00 Memo Quality Control

Picklist Print

January-10-13 3:10:08 PM

Work Order ID:

95526

Parent Item:

D3957-4

Parent Item Name:

Hinge, Door RH Lower

Start Date: 1/10/13

Required Date: 1/16/13

Start Qty: 4.00

Required Qty: 4.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6B0.750X03.000		Purchased	No			100	f	20.5780	0.266	1.12			.,
6061-T6 Bar .750 x 3.00									920-0 to 5-6		77-24 TA		******************
				Location		Loc Oty	<u>Lo</u>	c Code					
				MAT049		20.578						1	
				104	741	20.494				1.12		13/0	//.
				152	11	0.084						,	

Page 1

DART AEROSPACE LTD	Work Order:	113340
Description: Hinge, Door RH Lower	Part Number:	D3957-4
Inspection Dwg: D3957 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST


X First Article	Prototype
-----------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.69	+/-0.030	0.684	7		Veca	6A-01
0.281	+/-0.010	0.277	~		4)	1)
0.281	+/-0.010	0.281	/		11	4
3.00	+/-0.030	3.000	~		1)	
R0.13	+/-0.030	RO.125	~		R-6	scf.
0.563	+/-0.010	0.562	~		Vern	6A-01
1.25	+/-0.030	1.260	1		h	()
1.93	+/-0.030	1,944	1		(1	1)
107°	+/-0.5°	1070	/		Analo Meter	CNC-03
0.250	+/-0.010	0.255	/		Vein	6A-01
Ø0.203	+0.005/-0.001	\$0.204	\		n ,	1)
1.170	+/-0.010	1.170	\		11	ı
0.39	+/-0.030	0,378	1		11	£1
0.33	+/-0.030	0.332	/		14-6	31006
Ø0.063	+0.004/-0.001	\$0.065	/		Vun	6A-01
0.125	+/-0.010	0.128	/		14-6	31006
0.094	+/-0.010	0.094	/		11	11
0.12	+/-0.030	0.150	>		Vein	6A-01
R0.50	+/-0.030	RO.500)		R-6	ref.


	OA 9		100		
Measured by:	۵۵ م.ط	Audited by:	04	Prototype Approval:	N/A
Date:	13/01/13	Date:	73 .1.14	Date:	N/A

Rev	Date	Change	Revised by 1 A	Approved
Α	09.12.14	New Issue	KJ 9	
			~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	•


	U		,		· /	1
ITEM	QTY -041	QTY -042	QTY -043	QTY -044	PART NUMBER	DESCRIPTION
1	X				D3957-041	HINGE ASSEMBLY, DOOR LH UPPER
2		Х			D3957-042	HINGE ASSEMBLY, DOOR RH UPPER
3			Х		D3957-043	HINGE ASSEMBLY, DOOR LH LOWER
4				Х	D3957-044	HINGE ASSEMBLY, DOOR RH LOWER
5	1		 	-	D3957-1	HINGE, DOOR LH UPPER
6		1			D3957-2	HINGE, DOOR RH UPPER
7			1		D3957-3	HINGE, DOOR LH LOWER
8				1	D3957-4	HINGE, DOOR RH LOWER
9	1	1	1	1	D3518-3	ROD END
10	1	1	1	1	MS124818	HELICOIL, 3/8-24 UNF
11	1	1	1	1	NAS509-6	NUT




D3957-041 HINGE ASSY, DOOR LH UPPER



D3957-043 HINGE ASSY, DOOR LH LOWER




D3957-042 HINGE ASSY, DOOR RH UPPER





D3957-044 HINGE ASSY, DOOR RH LOWER




Α	NEW ISS	SUE		16	09.09.03			
REV.			DESCRIPTION	BY	DATE			
DESIG	N	3 5	DART AEROSPACE LTD					
DRAW	7	3 5-	HAWKESBURY, ONTARIO, CANADA					
CHECK	ED	PH.	DRAWING NO.	REV. A				
MFG. APPR.		94	□ D3957		SHEET 1 OF 5			
APPRO	APPROVED 16		TITLE		SCALE			
DE APP	R.	-#	HINGE		NTS			
DATE	09.0	9.03	THIS COCUMENT IS PRIVATE AND CONFIDENTS NOT TO BE USED FOR ANY PURPOSE OR COR		CONDITION THAT IT IS			









•